

StarFire™ 6000 and StarFire™ 6000 Integrated Receiver

Software Update 22-1 Release Notes
4.60H

Resolved Items:

AutoTrac Line Jumps on RTK

A bug was fixed to correct an issue with RTK towers building up error causing AutoTrac lines to shift quickly or jump. This bug can also affect shared signal.

Additional minor bug fixes

Release Notice

These are software release notes for the StarFire™ 6000 and StarFire™ 6000 Integrated Receiver. Release Notes can be found on www.stellarsupport.com. Note: Your use of the software is governed by the End User License Agreement included with the software.

Copyright © 1996-2022 Deere & Company